

MOUNTING GUIDE FOR TBMINIFIGSHLF-10

6 in



USE SCREW TO PUNCTURE THE CENTER OF EACH TARGET TO MARK DRILL HOLES